PAEX PROJECTS & INFASTRUCTURE REPAIRS – 2022

- 1) Campground install tin over existing fencing to a) keep unsitely grounds north and in behind Walmart area. b) try to curtail noise issues caused by walmart refers running after 11:00 p.m. and between hours all night to 7:00 a.m.
- 2) Replace pole fence located on the inside track of the grandstand area.
- 3) Major clean-up and paint the grandstand seating area.
- 4) Major fence repairs.
- 5) Major overhaul/painting and leaning of Public Washrooms building.
- 6) Sewer backup and repairs in Campground area.
- 7) Sewer backup and repairs in Permanent booth area.
- 8) Mechanical work on Green Tractor leaks.
- 9) Stain all corals.
- 10) Stain barn doors.
- 11) Repair burned section on tower located by main ring.
- 12) Paint lines in parking lot.
- 13) Organized back storage off old servery.
- 14) Organized garage.
- 15) Mechanical work zero turn land-pride lawnmower.
- 16) Mechanical work on all small motor equipment.
- 17) Shingles repair to roof of kiosks.
- 18) John Deer tractor mechanical issues repaired.
- 19) Built a pepsi enclosure & painted in new servery.
- 20) Bar & kitchen counter extensions made.
- 21) Fixed roof vent on public washrooms.
- 22) Replaced siding on kiosks caused by vandalism.
- 23) Replaced Facia missing on log house.
- 24) Replace boards and broken screws on deck of Pioneer log house.
- 25) Ceiling in garage falling apart repaired.
- 26) Electrical switch moved in women's bathroom.
- 27) Mechanical work zero turn Ferris lawnmower installed new motor.
- 28) Maintenance on gator; grease fittings; replaced oil.
- 29) Replaced plywood in back of gator.
- 30) Replaced oil in John Deer Tractor; flush radiator and replace coolant;
- 31) Welding chairs (approx. 60).
- 32) Repaired Ford F350 break-line.
- Repaired heater motor located in foyer of Optimist building.
- Repaired and or replaced facets in men's and women's washrooms.
- 35) Replaced toilet in men's washroom.

- 36) Repaint chuckwagon used for CPCA advertising.
- 37) Roof repairs on barns and main hall.
- 38) Fixed furnace located on main building.
- 39) Fence repairs ongoing.
- 40) Tree trimming arborist work ongoing
- 41) Yearly inspections done on fire extinguishers; fire alarms; main kitchen suppression; Optimist building boiler.